












PSM-MA-1_7

1 OF 7

01-00	 X1	13-00	 X1
09-00	 X2	12-00	 X1
	Bearing seat  X2		 X1
21-00	 X1		

PSM-MA-2_7

2 OF 7

04-00	 X2	06-00	 X1
02-B	 X1	02-A	 X1




PSM-MA-3_7

3 OF 7

[illegible]







PSM-MA-4_7

4 OF 7

03-00	 X1	20-00	 X1
14-00	 X1		


PSM-MA-5_7

5 OF 7

07-00	 X1	16-00	 X4
15-00	 X1	17-00	 X1
05-00	 X1	10-00	 X1


PSM-MA-6_7

6 OF 7



X1




18&19



X1





PSM-MA-6_7

6 OF 7

	M16*85 bolt,nut,washer  X7		M16*100 bolt,nut,washer  X2
	M16*95 bolt,nut,washer  X12		M16*90 bolt,nut,washer  X21
	M16*85 bolt,nut,washer  X3		M16*80 bolt,washer  X6
	M16 nut, washer,spring washer  X3		









PSM-MA-6_7

6 OF 7

	M12*95 bolt,nut,washer  X8		M12*70 bolt,nut,washer  X4
	M12*25 bolt,washer  X4		M10*85 bolt,washer  X4
	M10*65 bolt,washer  X1		M10*20 bolt,washer  X2

PSM-MA-7_7

7 OF 7

07-00	 X3		 X1
			 X1
22-00	 X2		 X1
			 X2
23-00	 X2		 X3
24-00	 X1		